Method of and apparatus for inspecting surfaces for defects

Patent number:

EP0405806

Publication date:

1991-01-02

Inventor:

MAGUIRE SEAN PATRICK JOSEPH (GB):

SIVAYOGANATHAN KANDIAH (GB); BALENDRAN

VELUPILLAI (GB)

Applicant:

JAGUAR CARS (GB)

Classification:

- international:

G01B11/30; G01N21/88

- european:

G01N21/88

Application number: EP19900306558 19900615

Priority number(s): GB19890015093 19890630; GB19890020358 19890908

Also published as:

US5086232 (A1) JP3042559 (A) EP0405806 (A3)

EP0405806 (B1)

Cited documents:


GB2159271 GB2133871 WO8907235 JP58204350

JP53057087

Report a data error here

Abstract of EP0405806

A method of inspecting a surface of a member such as a motor vehicle body panel (11) includes the steps of setting up the member at an inspection site, directing light (20) on to the surface at a high angel of incidence so as to form a transverse trace (24) across the surface and to reflect light (22) from the surface with a low angle of deflection to form an image (25) of the trace on a detection screen (23). A record of the image is produced. The trace is also viewed and recorded directly from a position (31) substantially perpendicular to the surface. The records of the image and of the trace are analysed together to give an indication of the nature of the surface at the trace. The light is scanned in relation to the member to form further transverse traces across the member and the new traces and images are also analysed.



Data supplied from the esp@cenet database - Worldwide



11) Publication number:

0 405 806 A2

(₂)

EUROPEAN PATENT APPLICATION

21 Application number: 90306558.9

(5) Int. Cl.5: G01N 21/88

② Date of filing: 15.06.90

Priority: 30.06.89 GB 8915093 08.09.89 GB 8920358

Date of publication of application:02.01.91 Bulletin 91/01

Designated Contracting States:
 DE FR GB IT SE

Applicant: JAGUAR CARS LIMITED Browns Lane Allesley Coventry CV5 9DR(GB)


2 Inventor: Maguire, Sean Patrick Joseph

27 Hereford Close
Barwell, Leicestershire LE9 8HP(GB)
Inventor: Sivayoganathan, Kandiah
30 Salisbury Street
Beeston, Nottingham NG9 2EQ(GB)
Inventor: Balendran, Velupiliai

39 Cotton Lane Moseley, Birmingham B13 9SB(GB)

Representative: Cundy, Anthony Brian et al Anthony Cundy & Company 384 Station Road Dorridgedge
Solihuli West Midlands B93 8ES(GB)

- (S) Method of and apparatus for inspecting surfaces for defects.
- (a) A method of inspecting a surface of a member such as a motor vehicle body panel (11) includes the steps of setting up the member at an inspection site, directing light (20) on to the surface at a high angel of incidence so as to form a transverse trace (24) across the surface and to reflect light (22) from the surface with a low angle of deflection to form an image (25) of the trace on a detection screen (23). A record of the image is produced. The trace is also viewed and recorded directly from a position (31) substantially perpendicular to the surface. The records of the image and of the trace are analysed together to give an indication of the nature of the surface at the trace. The light is scanned in relation to the member to form further transverse traces across the member and the new traces and images are also analysed.



METHODS OF AND APPARATUS FOR INSPECTING SURFACES FOR DEFECTS

10

30

The invention relates to a method of inspecting surfaces of members for defects.

Members such as motor car body panels which are produced in large numbers may include some members or panels with defects. With steel body panels local defects such as surface pitting can occur but also on pressing of the panels, some may be manufactured with a defective shape.

In a finished motor car the most prominent way in which defects show up 'is in irregular distortion of reflections from a high-gloss finish. Regular distortion is of course to be expected due to the curvature of a panel.

It has already been proposed in the LORIA (Trade Mark) surface analyser system of Ashland Chemicals to analyse or inspect the surface of a panel by reflecting a laser beam from a panel onto a screen at a high angle of incidence to give a low angle of deflection (that is a small deflection from the incident direction) in the beam, scanning the beam across the panel to form a trace, recording the image of the trace on the screen, similarly producing traces, images and records for successive parts of the panel, and analysing the records of the images to give a measure of the shape and surface quality of the panel. The present invention is concerned with an improvement to a system of this kind.

The known system can be effective for detecting some surfaces with small degrees of curvature and small irregularities but some kinds of contour of the panel can not be detected effectively and accurately.

An objective of the present invention is to provide an improved system in which the above disadvantages are reduced or overcome.

In accordance with the present invention there is provided a method of inspecting a surface of a member including the steps of setting up the member at an inspection site, directing light on to the surface at a high angle of incidence so as to form a trace thereacross and to reflect light from the surface with a low angle of deflection (that is a small deflection from the incident direction) to form an image of the trace on a detection screen, producing a record of the image, viewing and producing a record of the trace of light on the surface from a position substantially perpendicular thereto, analysing the record of the image and the record of the trace together to give an indication of the nature of the surface at said trace, scanning the light in relation to the member to form further transverse traces across the member and repeating the remaining steps for the new traces.

In addition to the data associated with the

geometry of the Incident light and the image on the screen, the substantially perpendicular view provides additional data relating to the line of contact of the incident light on the panel. By analysing data from both the reflected image and its trace on the panel together, an improved indication as to the nature of the surface can be established.

Preferably the incident light is generated by a laser and preferably this laser operates within, the visible spectrum.

Preferably the incident light forms a trace across the panel lay being focused into a fan shaped beam, the cross section of which is a transverse line, but alternatively the trace could be formed by a narrow beam of light, which scans across the panel in a transverse line.

Although a useful degree of analysis of a surface can be carried out by visual inspection and comparison of images and traces, computer analysis results in a very powerful tool. Data representing the shape of the panel may be analysed by deriving that bivariate third order polynomial which gives the best possible fit with the data and employing error signals between the polynomial arid the actual data as a measure of the acceptability of the surface. The computerised system is then appropriate for automatic or semi-automatic inspection techniques enabling it to reject or accept individual panels. In the context of motor vehicle body panels, this kind of inspection technique can improve the quality of a motor car body.

The system is useful for flat or nearly flat car body panels including for example door skins and boot and bonnet lids. For more deeply shaped parts such as typical wing panels, the technique can not normally be applied because the extreme curvature of such panels renders them unsuitable for scanning the whole surface. It might be possible to test relatively flat parts of these very curved panels but results are unlikely to be sufficiently valuable to warrant the expense.

An embodiment of tile invention will now be described with reference to the accompanying drawings in which:-

Figure 1 is a diagramatic layout drawing of a complete apparatus for performing the invention; Figure 2 is a plan view showing part of the arrangement for Figure 1; and

Figure 3 illustrates the formation of an image on a screen in the arrangement of Figures 1 and 2.

Figure 1 illustrates an installation for carrying out a method of inspecting the surface of a member 11 for defects. In this example the member 11 is a door panel for a motor vehicle body in a condition known in the industry as "body in white"

45

50

10

35

40

45

50

55

0 , 5

or "BIW". This is a sheet steel pressing to which no paint or other surface coating has been applied. It may be necessary in some cases to coat the surface with a reflective material to achieve a sufficiently clear reflection. The method could however be used for inspecting other types of surface such as painted surfaces or surfaces of plastics mouldings or of glass fibre reinforced plastics.

The apparatus comprises a horizontal bed 12 on a supporting structure 13. A table 14 is mounted on the bed 12, runs along the table on rollers 15 and is accurately constrained so that it moves only linearly.

A stepper motor unit 16 drives a pulley 17 which in turn drives the table 14 via a cable 10 and drive bracket 19. In use, the body panel is mounted positively on the table 14 and thus it can be indexed in steps or moved continuously in the longitudinal direction of the bed 12.

A source of coherent visible light, for example, a 5mW He Ne laser 21 is mounted in a fixed position such that its output is directed at the panel with a high angle of incidence so as to produce reflected light with a low angle of deflection, that is with a small deflection from its incident direction. hn incident angle of the order of 85° giving a deflection of about 10° is suitable. There is a requirement for the laser beam to impinge on the whole width to be inspected. This may be achieved by a narrow beam focused to a single point and traversed across the surface of the panel but preferably the laser output is focused into a fan shaped planar beam 20 so that at any instant it impinges on the whole width to be inspected. For narrow panels of 20 or 30 cm width, the whole width of the panel is inspected in one pass. For wider door panels, the panel may be inspected ill several separate passes to cover its whole width.

A significant portion of the light is reflected as from a mirror as indicated by arrows 22 and forms an image on a screen 23 arranged substantially perpendicular to the longitudinal direction of the bed 12 and the direction of the incident light from laser 21. If the surface of the panel is not sufficiently reflective in itself it should be made more reflective by means of a suitable coating. The generation of the image is best illustrated in Figure 3. The flat fan shaped incident beam 20 is shown to impinge on the panel 11, forming a trace 24 on the panel. This trace is curved due to the curvature of the body panel and the curvature of the actual trace 24 is amplified due to the high angle of incidence. The directly reflected light 22 then impinges on screen 23 to form an image 25. Image 25 conforms generally to the cross-sectional shape of the panel but its curvature is magnified by the divergence of the beam and is distorted (in this example elongated) by outward deflection due to

the curvature of the panel.

Figure 1 shows a first camera 26 directed at the screen 23 to record the image 25 formed on the screen. The camera is connected to a vision system 27 which displays the image as 25A on a monitor 28. Signals or data representing a record of the image 25 are also transmitted to a computer 29 for analysis.

A second camera 31 is arranged directly above the panel 11 and is directed at the region where the laser beam impinges on the panel to form the trace 24. Some of the light incident on the trace is scattered rather than being reflected with the result that the trace is visible from various angles and can be recorded by camera 31. The output from camera 31 representing the trace 24 is fed to a vision system, in this example the same vision system as used for camera 26. The trace may be displayed on screen 28 if required. Signals or data representing a record of the trace are transferred to computer 29.

The incident light beam of necessity has a significant depth with the result that the trace 24 and image 25 have significant depth. For accurate resolution an edge of the trace or image is defined by the position at which a threshold light level is achieved. The definitive line of the trace or image may be taken as one of these edges or the mean position of the two edges.

In use, the table 14 carrying tlie panel 11 is stepped in increments of a few millimetres along the bed 12. In this way, the laser beam is effectively indexed along the panel. An image 25 and trace 24 are recorded for each indexed position, building up a family of traces and images. By way of example, a series of such images are shown on the monitor 32 of computer 29. As an alternative the panel could move continuously, traces and images being recorded at specific intervals.

In this way, a series of images and traces representing the transverse curvature of the panel may be viewed simultaneously, facilitating judgement as to the quality of the panel.

The data collected during scanning of the panel gives a complete representation of its shape and this shape is analysed if, the computer in the following way. A simplified representation of the actual measured shape is derived in the form of that bivariate third order polynomial which gives the best possible fit between the actual surface and the derived polynomial. For a regularly curved panel, the bivariate third order polynomial will fit reasonaly closely to the actual panel but for an irregularly curved panel there will be substantial differences or errors between the polynomial and the actual shape.

These error signals may be displayed as colour signals superimposed on a family of curves 5

20

35

such as shown on screen 32, with different colours representing different ranges of magnitude. An operator may inspect the colour coded display and accept or reject a panel on the basis of a subjective judgement of the significant presence of colours representing large error signals. Alternatively, panels could be rejected automatically on the basis of a particular level of error signal.

With the inspection and analysis just described, irregularities in the surface are detected but the panel is not compared with a standard reference panel. Comparison with a standard panel may be achieved by other means or may not be necessary.

With an alternative analysis procedure, the computer may be loaded with a bivariate third order polynomial which defines an ideal shape for the surface. Rather than calculating this polynomial, it could be derived by inspection of a series of panels known to be of the required shape and averaging the signals derived therefrom.

The signals representing a family of images and traces from a panel being inspected would then be compared with and fitted to the standard polynomial in such a way as to effectively position the panel in register with the ideal shape. Error signals representing the departure of the actual surface front the ideal are derived. These may be displayed as before or used for automatic acceptance or rejection.

Although processing of the Image 25 alone can produce useful results and similarly processing of traces 24 as recorded in camera 31 can likewise give useful results, combining the information from the image 25 and the trace 24 gives a more effective indication of the nature of the surface.

The data from the two cameras is complementary as will now be explained.

The data recorded by the first camera 31 completely fixes the position in space of a point on the panel, but with low resolution. In particular, the point is known to lie in the fixed plane of the incident light and its position along and across this plane is recorded by camera 31 which observes a view substantially perpendicular to this plane. However the resolution is not good because the plane of the light and the surface being detected are at very shallow angles with respect to each other leading to a line of intersection which is not sharply defined.

The data recorded in the second camera from the image is in itself ambiguous in that it represents a combination of panel position and panel angle; the same image point on the screen could be achieved by reflections at different angles from different positions in the plane of the incident light. However the screen is substantially perpendicular to the reflected light giving a sharper high resolu-

tion image.

By combining data from the low resolution accurate position trace and the high resolution ambiguous positive image, a particularly clear definition of the panel can be achieved.


Claims

- 1. A method of inspecting a surface of a member (11) including the steps of setting up the member at an inspection site, directing light (20) on to the surface at a high angle of incidence so as to form a transverse trace (24) thereacross and to reflect light (22) from the surface with a low angle of deflection to form an image (25) of the trace on a detection screen (23), producing a record of the image and scanning the light in relation to the member to form further transverse traces across the member, characterised by the further steps of viewing and producing a record of one trace of light on the surface from a position (31) substantially perpendicular thereto, analysing the record of that image and the record of that trace together to give an indication of the nature of that surface (11) at said trace (24), and repeating the viewing, recording and analysis steps for the new traces.
- 2. A method as claimed in Claim 1 characterised in that the light source is a laser (21).
- A method as claimed in Claim 1 or Claim 2 characterised in that the light is focused in to a fan shaped planar beam (20) to form the trace (24) across the surface.
 - 4. A method as claimed in Claim 3 characterised in that one edge of the trace or image representing an edge of the beam is recorded as representative of the trace or image.
 - 5. A method as claimed in any one of the preceding claims characterised in that data representing the shape of the panel is analysed by deriving that bivariate third order polynomial which gives the best possible fit with the data and employing error signals between the polynomial and the actual data as a measure of the acceptability of the surface.
- 6. A method as claimed in any one of the preceding claims characterised in that signals representative of the actual shape of the surface of the member are derived from the image and trace signals and are compared with previously recorded data representing an ideal shape to provide error signals indicative of defects.
 - 7. A method as claimed in claim 6 characterised in that the errors are displayed in ranges of magnitude.
 - 8. Apparatus for carrying out the method as claimed in any of the preceding claims including a table (14) for supporting a member, a source of light (21) set to be incident on the table at a high


angle of incidence, a screen (23) arranged to receive an image reflected from the surface of the member and means (26, 27) for recording the form of the image, characterised by the provision of means (31) for viewing the trace of the beam on the member from a position substantially perpendicular to the member and means (29) for deriving signals indicative of the shape of the member from the received image and trace signals.

·

40 .



:-



This Page is inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS	
IMAGE CUT OFF AT TOP, BOTTOM OR SIDES	
FADED TEXT OR DRAWING	
BLURED OR ILLEGIBLE TEXT OR DRAWING	
SKEWED/SLANTED IMAGES	
☐ COLORED OR BLACK AND WHITE PHOTOGRAPHS	
☐ GRAY SCALE DOCUMENTS	
☐ LINES OR MARKS ON ORIGINAL DOCUMENT	
☐ REPERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALIT	Y
□ OTHER:	

IMAGES ARE BEST AVAILABLE COPY.
As rescanning documents will not correct images problems checked, please do not report the problems to the IFW Image Problem Mailbox